

Basic Vehicle Condition Guide

Report ID: 17,982,503


Version: 1

Created: 09 May 2019

Make: Model: Mitsubishi 380 **Body Style:** Sedan Year: 2006 Registration: DCL943 Reg Expiry: 03 Jan 2020 WoF Expiry: **Odometer:** 30 Apr 2020 93,769 Kms **Good No:** 17982503 VIN: 6MMDB4X415T00681 Next Service: 103800 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Boot spoiler and roof needs paint,

| Conditions During Body Inspection: | Dry |
|------------------------------------|-----|
|------------------------------------|-----|

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | 5 |
|-------------------|---------|
| Seats | Average |
| Carpets | Average |
| Panels | Average |
| Dashboard | Average |

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

| Create | u. 0. | 7 IVIGY 2 | | | | |
|--|---------------------------------------|-----------|-----|--|--|--|
| | Pass | Fail | N/A | | | |
| Engine | | | | | | |
| Oil level | ~ | | | | | |
| Smoke & fumes | V V | | | | | |
| Performance | ~ | | | | | |
| Noise | ~ | | | | | |
| Cooling System | | | | | | |
| Coolant condition | ~ | | | | | |
| Performance | ~ | | | | | |
| Radiator / Hoses (visual) | ~ | | | | | |
| Transmission | | | | | | |
| Operation | ~ | | | | | |
| Noise | ~ | | | | | |
| Clutch | | | ~ | | | |
| CV joints | ~ | | | | | |
| Wheel bearings | ~ | | | | | |
| Brakes | | I | | | | |
| Performance | ~ | | | | | |
| Hand Brake | ~ | | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | | |
| Left front | 7 | | mm | | | |
| Right front | 7 | | mm | | | |
| Left rear | 7 | | mm | | | |
| Right rear | 7 | | mm | | | |
| Spare | | Yes | | | | |
| Suspension | | | | | | |
| Suspension performance | ~ | | | | | |
| Steering performance | ~ | | | | | |
| Shock absorbers | ~ | | | | | |
| Air Conditioning / Heater | | | 1 | | | |
| Operation | ~ | | | | | |
| Electrical / Accessories | | | | | | |
| Head lights | ' | | | | | |
| Tail lights | ~ | | | | | |
| Indicators | ~ | | | | | |
| Dashboard warning lights | ~ | | | | | |
| Wipers (front & rear) | ~ | | | | | |
| Window winder FL | ~ | | | | | |
| Window winder FR | ~ | | | | | |
| Window winder RL | ~ | | | | | |
| Window winder RR | V V V V V V V V V V V V V V V V V V V | | | | | |
| Rear view mirrors | ~ | | | | | |
| Radio (basic test only) | ~ | | | | | |
| CD (basic test only) | ~ | | | | | |
| Number of keys | 2 | <u> </u> | | | | |
| Central locking | | | | | | |
| Remote locking | | | | | | |
| Sat. Nav. (basic test only) | | | ~ | | | |
| Reversing camera | | | ~ | | | |
| | | | | | | |

I have read and understood this condition guide.

Donovan Matara

Name:

Signature:

09 May 2019

Date: