

## **Basic Vehicle Condition Guide**

Report ID: 17,982,574

Pass

Version:

Created: 16 Apr 2019


Fail

N/A

Make: Holden Model: Viva **Body Style:** Wagon Year: 2006 Registration: DDC574 **Reg Expiry:** 11 Apr 2019 WoF Expiry: **Odometer:** 20 Dec 2019 251,555 Kms **Good No:** 17982574 VIN: KL3NA35BJ6K295137 **Next Service:** 0 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Minor oil leak, slight rattle and knocking noise,

Interior Comments		
Seats	minor stains, wear and tear ,	
Carpets	Average	
Panels	LR door trim ripped ,	
Dashboard	Average	

	_
General	Comments

Inspected by:

**Road Conditions During Test Drive:** Dry

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** Yes

Donovan Matara

Kms: 122,138 Engine Oil level Smoke & fumes 1 Performance V Noise / Cooling System Coolant condition Performance Radiator / Hoses (visual) **Transmission** Operation V Noise 1 Clutch 1 CV joints Wheel bearings Brakes Performance **Hand Brake** Tyres (lowest observed tread depth of tyres) Left front mm Right front 1.5 mm Left rear mm Right rear 1.5  $\mathsf{mm}$ Spare Yes Suspension Suspension performance Steering performance 1 Shock absorbers Air Conditioning / Heater Operation **Electrical / Accessories** Head lights Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors / Radio (basic test only) 1 CD (basic test only) 1 Number of keys 1 Central locking Remote locking Sat. Nav. (basic test only)

I have read and understood this condition guide.

Name: .....

Signature: .....

16 Apr 2019

Reversing camera

Date: