

## **Basic Vehicle Condition Guide**

Report ID: 17,982,672


Version: 1

Created: 16 Apr 2019

Make: Model: Mitsubishi Triton **Body Style:** Utility Year: 2017 Registration: KFY990 Reg Expiry: 27 Feb 2019 WoF Expiry: **Odometer: Good No:** 28 Feb 2020 61,860 Kms 17982672 VIN: MMAJJKK10HH00777! Next Service: 65000 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Stone chips in the windscreen,

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>	
Seats	cigarette holes in bas bases ,
Carpets	Average
Panels	Average
Dashboard	Average

## **General Comments**

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Inspected by: Donovan Matara

I N/A
1
_
res)
mm
mm
mm
mm
5
1
\ <u>\</u>
+

I have read and understood this condition guide.

Name: .....

Signature: .....

16 Apr 2019