

Report ID: 17,983,053

Version: 2


Created: 23 Apr 2019

Fail N/A

| Make: | Mazda | Model: | MPV2300 | Body Style: | SUV |
|-------------|-------------------|---------------|-------------|----------------|-------------|
| Year: | 2004 | Registration: | GGQ436 | Reg Expiry: | 07 Sep 2018 |
| WoF Expiry: | 08 Jun 2018 | Odometer: | 194,632 Kms | Good No: | 17983053 |
| VIN: | 7AT0C11EX11412461 | Next Service: | 0 | Service Histor | y: No |

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

LF door side mirror glass broken, minor stone chips in the windscreen,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Minor oil leak,

| <u>Interior Comments</u> | | | | |
|--------------------------|--|--|--|--|
| Seats | seats ripped, stained, wear and tear , | | | |
| Carpets | wear and tear,stained , | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

General Comments

ABS light is on,TCS light is on,car has a shudder when idling, hand brake light stays on,

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Donovan Matara 23 Apr 2019 Inspected by: Date:

| Engine | | | |
|------------------------------|---------|--------|-----|
| Oil level | | ~ | |
| Smoke & fumes | ~ | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | | ~ | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d deptl | of tyr | es) |
| Left front | 1 | .5 | mm |
| Right front | 1 | .5 | mm |
| Left rear | 2 | | mm |
| Right rear | | 2 | mm |
| Spare | | Yes | |
| Suspension | • | | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | • |
| Operation | | ~ | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | | | ~ |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | | | ~ |
| | | 1 | |

I have read and understood this condition guide.

Name:

Signature: