

Report ID: 17,983,547 Version: 1 02 May 2019 Created:

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2000	Registration:	DRL938	Reg Expiry:	18 Jul 2019	Engine	1	1	1
WoF Expiry:	18 Jan 2020	Odometer:	176,810 Kms	Good No:	17983547	Oil level	~		
VIN:	WVWZZZ1JZYP38109	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		<u> </u>
				·		Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	r		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	SC W			Radiator / Hoses (visual)	~		
S = scratch						Transmission	Transmission		
D = dent R = rust	s sc			ZIS	SPT	Operation	~		
PT = paint defe				$\left[\right] \left[\right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIC				74114	CV joints	~		
* = decals	s sc gle			-No-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC S SC S SC S P SC						Performance	~		
Dedution		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	Tyres (lowest observed tread depth of tyr		
Minor stone chips in the windscreen ,									mm
						Right front		5	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear		5 mm	
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor oil le	ak,					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation		~	
Interior Comments						Electrical / Accessories	I	-	1
Seats	drivers sea	at ripped,wear ar	nd tear ,			Head lights	~		
	duit care fle					Tail lights	~		
Carpets	drivers flo	or ripped,				Indicators	~		+
Panels	interior tri	m panels coming	g off different areas,			Dashboard warning lights	~		
			incipa			Wipers (front & rear)	~		
Dashboa	rd surround a	around stereo mi	issing ,			Window winder FL	~		
	1				J	Window winder FR	~		
<u>General Comments</u> Has 2 different keys one opens door and the other starts the car,						Window winder RL	~		<u> </u>
						Window winder RR	~		+
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		<u> </u>
						Number of keys	1	I	L
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Road Conditions During Test Drive: Dry						Remote locking	-	r	+
Engine Ti	ming Mechanism:	Cambel	t			Sat. Nav. (basic test only)		-	~
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 17	1,634	Reversing camera			~
L									
Inspected by: Donovan Matara Date: 02 May 2019									

I have read and understood this condition guide.

Name:

Signature: