

Report ID: 17,984,135 Version: 1 17 May 2019 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A
Year:	2011	<b>Registration:</b>	HLL267	<b>Reg Expiry:</b>	21 Aug 2019	Engine			•
WoF Expiry:	17 Jan 2020	Odometer:	107,702 Kms	Good No:	17984135	Oil level	~		
VIN:	MMACNKB40BD0067(	Next Service:	116900	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and ti	his can be arranged fo	or an additional o	narge.	Coolant condition	~		
	SC		S D S SC	S	S	Performance	~		
Key:		-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s sc			20		Operation	~		
PT = paint defe	ect NP				11111	Noise	~		
C = crack					S SC	Clutch	~		
P = pin dent	ssc dR				2416	CV joints	~		
* = decals		10		10	SD SD	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	SC	e	S P SC S P SC		S SC	Performance	~		
Body Insr	ection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Rear deck needs paint , both sills need paint ,						Tyres (lowest observed tread depth of tyres)			ès)
						Left front	3 mm		mm
						Right front	3	3	mm
						Left rear	2	2	mm
Conditions During Body Inspection: Dry						Right rear	2 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Comoto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	over spray	paint and other,	stains over panels ,			Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ru 🦿					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	-		•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 17 May 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....