

Basic Vehicle Condition Guide

Report ID: 17,984,807


Version: 2

Created: 07 Oct 2019

Make: Model: SUV Holden Captiva 5 **Body Style:** Year: 2011 Registration: GHK419 Reg Expiry: 27 Sep 2019 WoF Expiry: **Odometer: Good No:** 15 May 2020 160,800 Kms 17984807 VIN: KL3DF26FJAB092425 **Next Service:** 170800 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor stone chips in the windscreen,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

R/F outer CV Boot Minor seepage, Minor oil seepage lower engine area,

| Interior Comments | | | | |
|-------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

07 Oct 2019 Inspected by: Chris Buckley Date:

Name:

| l | | Dass | Fail | N/A | | | |
|-------|--|-----------------|------|------|--|--|--|
| | Engine | Pass | Fall | IN/A | | | |
| | Oil level | | | | | | |
| | Smoke & fumes | | | | | | |
| ! | Performance | V | | | | | |
| | Noise | ~ | | | | | |
| | Cooling System | | | | | | |
| | Coolant condition | ~ | | | | | |
| | Performance | ~ | | | | | |
| | Radiator / Hoses (visual) | ~ | | | | | |
| | Transmission | | | | | | |
| | Operation | ~ | | | | | |
| | Noise | | | | | | |
| | Clutch | ~ | | | | | |
| | CV joints | \(\times \) | | | | | |
| | Wheel bearings | ~ | | | | | |
| | Brakes | | | | | | |
| | Performance | ~ | | | | | |
| | Hand Brake | ~ | | | | | |
| | Tyres (lowest observed tread depth of tyres) | | | | | | |
| | Left front | 4.0 mm | | | | | |
| | Right front | 4.0 | | mm | | | |
| | Left rear | 4.0 | | mm | | | |
| | Right rear | 4.0 | | mm | | | |
| | Spare | | Yes | | | | |
| | Suspension | | | | | | |
| | Suspension performance | ~ | | | | | |
| | Steering performance | ~ | | | | | |
| | Shock absorbers | ~ | | | | | |
| | Air Conditioning / Heater | | | ! | | | |
| | Operation 🗸 | | | | | | |
| | Electrical / Accessories | | | | | | |
| | Head lights | ~ | | | | | |
| | Tail lights | ~ | | | | | |
| | Indicators | ~ | | | | | |
| | Dashboard warning lights | | | | | | |
| | Wipers (front & rear) | \(\triangle \) | | | | | |
| | Window winder FL | ~ | | | | | |
| | Window winder FR | ~ | | | | | |
| | Window winder RL | ~ | | | | | |
| | Window winder RR | ~ | | | | | |
| | Rear view mirrors | ~ | | | | | |
| | Radio (basic test only) | ~ | | | | | |
| | CD (basic test only) | ~ | | | | | |
| | Number of keys 2 | | | | | | |
| | Central locking | ~ | | | | | |
| | Remote locking | ~ | | | | | |
| | Sat. Nav. (basic test only) | | | ~ | | | |
| | Reversing camera | | | ~ | | | |
| | | | | | | | |

Signature: