

Basic Vehicle Condition Guide

Report ID: 17,985,636


Version: 2

Created: 29 Aug 2019

Make: Model: Holden Captiva 7 **Body Style:** SUV Year: 2016 Registration: KDS361 Reg Expiry: 25 Oct 2019 WoF Expiry: **Odometer:** 12 Sep 2020 39,994 Kms **Good No:** 17985636 VIN: KL3CD2659GB535008 Next Service: 49,000kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

- Poor paint repair to left front guard, left front door & left rear door, sanding marks & dirt in paint.

Conditions During Body Inspection:	Dry
------------------------------------	-----

Under Carriage & Under Bonnet Inspection Comments

Interior Comments	5
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Date: 23 Jul 2019 Inspected by: Jason Young

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	\(\times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission	•		•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	l	-	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	4	.8	mm
Right front	5	.0	mm
Left rear	3.8 mm		mm
Right rear	4	4.0 mm	
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	<u> </u>	1	
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights			
Indicators	\(\times \)		
Dashboard warning lights	<i>\sqrt{\sq}}}}}}}}}}}}}} \sqite\septionup\sign{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}}} \sqrt{\sq}}}}} \sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}} \sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sqrt{\sq}}}}}}}}}}}} \sqite\septionup\sint{\sint{\sint{\sint{\sint{\sint{\sq}}}}}}</i>		
Wipers (front & rear)			
Window winder FL	\(\triangle \)		
Window winder FR	~		
Window winder RL	<i>v</i>		
Window winder RR	~		
Rear view mirrors	<i>v</i>		
Radio (basic test only)	•		
CD (basic test only)			~
Number of keys	2		
Central locking	2 V		
Remote locking	•		
			.,
Sat. Nav. (basic test only)	.,		
Reversing camera	•		
Date: 22 Jul 201	^		

Signature: