

Basic Vehicle Condition Guide

Report ID: 17,990,601


Version: 2

Created: 13 Sep 2019

Make: Model: Holden Commodore **Body Style:** Sedan Year: 2011 Registration: GAQ706 **Reg Expiry:** 01 Nov 2019 WoF Expiry: **Odometer:** 25 Sep 2020 145,150 Kms **Good No:** 17990601 VIN: 6G1EK5E58BL533325 Next Service: 150,000kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

- Note: some defects & blemishes may not be displayed in the diagram
- Plastic covers missing that fit over both right & left front seat rail bolts.
 Left front bumper has been repainted around where stickers have been.
- Hole in roof & boot lid.
- Plastic trim on left side wing mirror is cracked

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | Good | Good | Carpets | Good | Panels | Average | Average | Average | Average | Carpets | Carp

General Comments

EX NZ POLICE VEHICLE:

- Some of buttons on steering wheel are not working.
- Front radio speakers are not working.
- Base missing to cup holder & pocket under heater controls.
- 4 x bolt holes in left front floor area.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jason Young Date: 16 Aug 2019

	Pass	Fail	N/A
Engine			•
Oil level	~		
Smoke & fumes	V		
Performance	~		
Noise	~		
Cooling System			•
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			1
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			1
Performance	~		
Hand Brake	~		
Tyres (lowest observed trea	d depth	of tyre	es)
Left front	7.2 mr		mm
Right front	7.2 mn		mm
Left rear	5.8 m		mm
Right rear	6.0 mn		mm
Spare	Yes		
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	1	ļ	
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V		
Wipers (front & rear)	~		

Window winder FL
Window winder FR

Window winder RL

Window winder RR

Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

1

/

1

/

1

1

~