

Basic Vehicle Condition Guide

Report ID: 17,991,710


Version: 3

07 Jan 2020 Created:

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2015 Registration: JGR506 Reg Expiry: 17 Apr 2020 **Odometer:** WoF Expiry: **Good No:** 02 Sep 2020 139,981 Kms 17991710 VIN: KMHST81XSFU510068 Next Service: 147,000kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Outer edge of left front tyre is worn.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Rear brake pads are wearing low, will need replaced soon.

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Jason Young

Create	Created: 07 Jan 2020				
	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	~				
Performance	\(\times \)				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	V				
Radiator / Hoses (visual)	~				
Transmission					
Operation	~				
Noise	V				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	<i>'</i>				
Tyres (lowest observed treac	l depth	of tyre) 		
Left front					
Right front			mm		
Left rear	3.0 1.8		mm		
Right rear	2.4		mm		
-					
Spare Yes Suspension					
Suspension performance	V				
Steering performance	V				
Shock absorbers	· ·				
Air Conditioning / Heater					
Operation Electrical / Accessories					
Head lights	·/				
Tail lights	· ·				
Indicators	V				
Dashboard warning lights					
Wipers (front & rear)	V				
Window winder FL	V				
Window winder FR	~				
Window winder RL	~				
Window winder RR					
Rear view mirrors	V				
Radio (basic test only)	<i>v</i>				
CD (basic test only)	<i>v</i>		-		
Number of keys	2		L		
Central locking					
Remote locking	<i>V</i>		-		
Sat. Nav. (basic test only)			.,		
Reversing camera	1				
eversing current					

14 Nov 2019

Date:

I have read and understood this condition guide. Signature: Name: