

Report ID: 17,991,768 Version: 1 20 Nov 2019 Created:

Make:	Toyota	Model:	Echo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2003		BJZ976	Reg Expiry:	23 Dec 2019	Engine			
	18 Apr 2020	Odometer:	218,275 Kms	Good No:	17991768	Oil level	~		
VIN:	JTDJW123200197768			Service Histor		Smoke & fumes	~		
	510511125200157700		220,330((11))			Performance	~		
	port is not a warranty		с I и			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
	ical inspection prior to					Coolant condition	~		1
						Performance	~		
Key:	DSC	-0	S D R P		S D P	Radiator / Hoses (visual)	~		
S = scratch	Se	10		10c	X	Transmission	V		
D = dent	ssc dl			The	BIDS	Operation			1
R = rust				10		Noise	マ マ		
PT = paint defe C = crack	ect M			+	S PT SC	Clutch	•		
C = Crack P = pin dent	Ho						~		
* = decals	S PT * SC DC					CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs SC S S D PT P S PT P						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	 	<u> </u>	Ļ
Missing badge off bonnet, paint clear coat is peeling off bonnet, roof, left side door & left rear guard. Small						Tyres (lowest observed tread depth of tyres)			
stone crack in left side of windscreen, stone chips in windscreen.						Left front	5.	.0	mm
						Right front	2	.0	mm
						Left rear	4	.0	mm
Conditions During Body Inspection: Dry						Right rear	4	.4	mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Spare Yes		
<u>Under Ca</u>	rriage & Under Bor	inet inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Deall	Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL		~	
						Window winder FR	~		
General Comments					Window winder RL			~	
Tuning knob on radio is missing. Central locking is not working.						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		1
						Number of keys	3		
Road Con	ditions During Test	t Drive:	Dry			Central locking		~	
			•			Remote locking	~		1
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected	d by: Jason Young	Date: 12 Nov 20	19						
I have read and understood this condition guide. Name:									