

Report ID: 17,996,134 Version: 1 Created: 05 Dec 2018

Make:	Toyota	Model:	Corolla	Body Style:	Wagon		Pass	Fail	N/A
Year:	2014		HGG800	Reg Expiry:	03 Feb 2019	Engine			L
WoF Expiry:		Odometer:	66,501 Kms	Good No:	17996134	Oil level	~		
VIN:	JTDZT4GE70L002138			Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent	SC DE			15	SW	Operation	~		
R = rust PT = paint def				$\prod$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIG				7411	CV joints	~		
* = decals	sc 916			-No-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs P W						Performance	~		
Body Incr		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments - Rear grab handles need reattached.						Tyres (lowest observed tread depth of tyr			es)
- Rear grab handles need reattached. - Roof has GSP dome.						Left front 4.0			mm
						Right front	4.		mm
						Left rear	3.		mm
Conditio	as During Body Ins	nection:	Dry			Right rear	3.		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension				
N/A						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
L						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
- No under	carriage inspection is av	ailable for this v	ehicle.			Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspecte	d by: Anna-Lise Fergu	1500				Date: 05 Dec 20	18		
inspecte	u by: Anna-Lise Fergl					Date: US Dec 20	10		

I have read and understood this condition guide.

Name: .....

Signature: .....