

Basic Vehicle Condition Guide

Report ID: 17,996,361


Version: 2

Created: 17 Apr 2019

Make: Model: Holden Cruze **Body Style:** Hatchback Year: 2012 Registration: GJZ432 Reg Expiry: 01 Jul 2019 WoF Expiry: **Odometer:** 08 Jun 2019 104,355 Kms **Good No:** 17996361 VIN: 6G1PE6E85CL652788 Next Service: ? Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

- Plastic wheel nut covers missing off right & left front wheels.
- Stone chips in windscreen.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

- Oil leak coming from front & right side of engine.
- Coolant system needs a flush, radiator.

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

- Knock coming from front suspension.
- Left side head rest missing off back seat.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: **Timing Chain**

Evidence of Cam Belt Replacement: Not Applicable Kms:

19 Dec 2018 Inspected by: Jason Young Date:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition		~	
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	1		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		l	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	3	.1	mm
Right front	2.1		mm
Left rear	6.8		mm
Right rear	6.9		mm
Spare		Yes	
Suspension			
Suspension performance		~	
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	>		
Electrical / Accessories			
Head lights	'		
Tail lights	~		
Indicators	\(\times \)		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Window winder RR	~		
Rear view mirrors	v		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)	~		
Reversing camera			~

I have read and understood this condition guide.

Name:

Signature: