

Basic Vehicle Condition Guide

Report ID: 17,996,943


Version: 1

Created: 21 Jun 2019

Make: Model: Toyota Corolla **Body Style:** Hatchback Year: 2015 Registration: JHR183 Reg Expiry: 07 Sep 2019 WoF Expiry: **Odometer: Good No:** 08 Sep 2019 74,660 Kms 17996943 VIN: JTNKU3JE80J103472 Next Service: 67,000kms **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

- Stone chips in windscreen.

| Conditions During Body Inspection: | Dry |
|------------------------------------|-----|
|------------------------------------|-----|

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | <u>5</u> |
|-------------------|----------|
| Seats | Good |
| Carpets | Good |
| Panels | Good |
| Dashboard | Good |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

18 Jun 2019 Inspected by: Jason Young Date:

Name:

| | Dana | Fa:I | N/A |
|------------------------------|--------------|---------|------------|
| Engine | Pass | Fail | IN/A |
| Oil level | ./ | | |
| Smoke & fumes | 1 | | |
| Performance | <i>V V</i> | | |
| Noise | 1 | | |
| Cooling System | | | |
| Coolant condition | ./ | | |
| Performance | 1 | | |
| Radiator / Hoses (visual) | 1 | | |
| Transmission | | | |
| | | | 1 |
| Operation Noise | | | |
| Clutch | · · | | |
| | _ | | \ <u>'</u> |
| CV joints | • | | |
| Wheel bearings | / | | |
| Brakes | | 1 | 1 |
| Performance | - | | |
| Hand Brake | <i>'</i> | | <u> </u> |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 5 | .6 | mm |
| Right front | 5.4 mm | | mm |
| Left rear | 6.0 | | mm |
| Right rear | 6 | .2 | mm |
| Spare | | Yes | |
| Suspension | | 1 | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | \(\times \) | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \(\times \) | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | <i>v</i> | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 2 | - | - |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | ~ | | |
| | | | |

Signature: