

Report ID: 17,997,252 Version: 1 Created: 26 Aug 2019

Make:	Toyota	Model:	Hiace	Body Style:	Van		Pass	Fail	N/A
Year:	2013	Registration:	GUA715	Reg Expiry:	09 Oct 2019	Engine	I	I	
WoF Expiry:	05 Apr 2020	Odometer:	215,765 Kms	Good No:	17997252	Oil level	~		
VIN:	JTFPT22P600010356	Next Service:	220,000kms	Service History	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	sc	-0	S SD		SP	Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch			~
P = pin dent						CV joints			~
* = decals SDPSC QQ						Wheel bearings			
SC = stone chips							~		
W = significant scuffs S S S D P S D						Brakes Performance			
Note come defects ? blamiches may not be displayed in the dispran							~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake			
						Tyres (lowest observed tread			-
						Left front		7.0 mm	
						Right front		.5	mm
						Left rear		.0	mm
Conditions During Body Inspection: Wet						Right rear	7.0 mm		mm
Under Carriage & Under Pennet Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension		1	
						Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		1	
						Operation	~		
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	iu					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
 Plastic trim on inside of drivers door has been tapped on to door frame. One of key remotes is not working to lock & unlock van. 						Window winder RR			~
		g to lock a unioc				Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	1	
Road Con	ditions During Tes	t Drive:	Wet			Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	′es	Kms: 14	6,265	Reversing camera	~		
ц								1	
Inspected by: Jason Young Date: 09 Aug 2019									
I have read and understood this condition guide. Name:									