

Report ID: 18,006,038 Version: 1 25 Mar 2019 Created:

Make:	Mercedes-Benz	Model:	CLS550	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	Registration:		Reg Expiry:	10 Sep 2019	Engine	I		L
WoF Expiry:		Odometer:	193,972 Kms	Good No:	18006038	Oil level	~		
VIN:	WDD2193722A13428	Next Service:	111548	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	unting is mode	for any and miles as	Danta hava nat	heen discontined or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	SSC S	-0	S SC S SC		sc	Radiator / Hoses (visual)	~		
S = scratch D = dent D = nut						Transmission			
						Operation	~		
R = rust PT = paint defe				\prod		Noise	~		
C = crack				+		Clutch	•		~
P = pin dent	HID				74 <u>11</u>	CV joints	~		•
* = decals	ssc 916			- NL	ELL'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S SC S SC S SC S SC						Performance	~		
Deskulas		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			es)
					Left front 7 mm				
						Right front	7		mm
						Left rear	7		mm
Conditions During Body Inspection: Dry						Right rear	7 mm		mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Steering performance						~			
Shock absorbers							~		
	Air Conditioning / Heater								
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
<u></u>	Average					Tail lights	~		
Carpets	Avelage					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	L.					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Donovan Matara Date: 25 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: