

Report ID: 18,007,051 Version: 1 30 Apr 2019 Created:

Make:	1/1.4			D 1 C 1	<u></u>		C	F	
	KIA	Model:	Sorento	Body Style:	SUV		Pass	Fail	N/
(ear:	2008	Registration:		Reg Expiry:	31 Aug 2019	Engine	1.		
	12 Apr 2020	Odometer:	217,054 Kms	Good No:	18007051	Oil level	~	ļ	<u> </u>
/IN:	KNEJC524875763574	Next Service:	227000	Service Histor	y: No	Smoke & fumes	~	 	
Note: This re	port is not a warranty					Performance	~	<u> </u>	
This report is	s a guide only. Consid	eration is made	for age and mileag	e. Parts have not	been dismantled or	Noise	~	<u> </u>	
	esting undertaken. The nical inspection prior to					Cooling System			1
	· ·		<u> </u>		J	Coolant condition	~	L	
Key:	S SC		S D SC S SC		S SC	Performance	~	ļ	
= scratch	~	$\overline{(0)}$		5(0)-	\checkmark	Radiator / Hoses (visual)	~		
) = dent					AD IS	Transmission			
= rust	S P SC				HIV	Operation	~	<u> </u>	
T = paint def	fect N					Noise	~	L	
= crack						Clutch		L	V
e pin dent = decals	s sc dl				1846	CV joints	~	L	
= decais C = stone chi		20		70		Wheel bearings	~		
l = significan	nt scuffs	$\underline{(0)}$		Z(Q)	~	Brakes			
2	S SC	\sim	S P SC S SC	\sim		Performance	~		
Body Ins	pection Comments	Note: som	ne defects & blemishe	es may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed trea	d depth	of tyre	2S)
						Left front	7	7	mr
						Right front		7	mr
						Left rear	4	4	mr
Conditions During Body Inspection: Dry						Right rear	4	4	mr
			•			Spare		Yes	
<u>Under Ca</u>	arriage & Under Bor	nnet Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~	ĺ	
						Air Conditioning / Heater			
						Operation	~		Γ
Interior Comments						Electrical / Accessories			
Contr	wear and							<u> </u>	T
Seats		tear,				Head lights		~	
	Average	tear ,				Head lights Tail lights	~	~	
Carpets	Average	tear ,					v v		
	Average Average	tear ,				Tail lights	-		
Carpets Panels	Average	tear ,				Tail lights Indicators	~		
Carpets	Average	tear ,				Tail lights Indicators Dashboard warning lights	v v		
Carpets Panels	Average	tear ,				Tail lights Indicators Dashboard warning lights Wipers (front & rear)	・ ・ ・ ・ ・		
Carpets Panels Dashboa	Average	tear ,				Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL	V V V V V V V V V		
Carpets Panels Dashboa	Average Average	tear ,				Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR	V V V V V V		
Carpets Panels Dashboa	Average Average	tear ,				Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR	V V V V V V V V V V V V V V V V V V V		
Carpets Panels Dashboa	Average Average	tear ,				Tail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder FRWindow winder RLWindow winder RRRear view mirrors	V V		
Carpets Panels Dashboa	Average Average	tear ,				Tail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder FRWindow winder RLWindow winder RRRear view mirrorsRadio (basic test only)	V V		
Carpets Panels Dashboa	Average Average	tear ,				Tail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder FRWindow winder RLWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)	V V		
Carpets Panels Dashboa	Average Average Average					Tail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder RRWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)Number of keys	V V V V V V V V V V V V 2		
Carpets Panels Dashboa	Average Average		Dry			Tail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder RRWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)Number of keysCentral locking	V V		
Carpets Panels Dashboa General G Road Con	Average Average Average Comments	t Drive:	•			Tail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder FRWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)CD (basic test only)Number of keysCentral lockingRemote locking	V V V V V V V V V V V V 2		
Carpets Panels Dashboa General G Road Con Engine Ti	Average Average Average Comments Comments Ming Mechanism:	t Drive: Cambelt	t	Kms:		Tail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder RRWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)CD (basic test only)Number of keysCentral lockingRemote lockingSat. Nav. (basic test only)	V V		
Carpets Panels Dashboa General G Road Con Engine Ti	Average Average Average Comments	t Drive: Cambelt	•	Kms:		Tail lightsIndicatorsDashboard warning lightsWipers (front & rear)Window winder FLWindow winder FRWindow winder RRRear view mirrorsRadio (basic test only)CD (basic test only)CD (basic test only)Number of keysCentral lockingRemote locking	V V		

I have read and understood this condition guide.

Name:

Signature: