

Report ID: 18,007,067 Version: 1 12 Mar 2019 Created:

Make:	Nissan	Model:	Pulsar	Body Style:	Hatchback		Pass	Fail	N/A
Year:	1998	Registration:	BLW513	Reg Expiry:	20 Jul 2019	Engine			
WoF Expiry:	20 Mar 2019	Odometer:	181,093 Kms	Good No:	18007067	Oil level	~		
VIN:	7A8DH0P0703863779	Next Service:	0	Service Histor	y: No	Smoke & fumes	r		
						Performance	r		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	S SC	-0	S P SC S P SC	-01-	P SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s c sc			715	HILS	Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				거네	CV joints	~		-
* = decals	ssc 916			- Jul	ALC S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan	s D SC		S SC S P SC		S SC	Performance	~		
Podylog	action Commonts	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			es)
Tailgate light cracked,small crack in the windscreen ,									mm
						Right front		3	mm
						Left rear	<u> </u>		mm
Conditions During Body Inspection: Dry						Right rear	5 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			I
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Weldge					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	•					Window winder FR	~		
<u>General C</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Centra							~		
			•			Remote locking			~
	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 12 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: