

diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	Cooling System		
	Coolant condition	~	
Kave SSC SD SDSC SDSC	Performance	~	
Key: 35C 35 35 35 35 35 35 35 35 35 35 35 35 35	Radiator / Hoses (visual)	~	
D=dent	Transmission		
	Operation	~	
PT = paint defect	Noise	~	
C = crack	Clutch		~
P = pin dent	CV joints	~	
edecais Disc	Wheel bearings	~	
SC = stone chips W = significant scuffs	Brakes		
SDSC SDSC SDSC SDSC	Performance	~	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram	Hand Brake	~	
body inspection comments	Tyres (lowest observed tread	depth	of tyres)
	Left front	6	mm
	Right front	6	mm
	Left rear	5	-
Conditions During Body Inspection: Dry	Right rear	5	
Conditions During Body inspection. Dry	Spare		Yes
Under Carriage & Under Bonnet Inspection Comments	Suspension		
	Suspension performance	~	
	Steering performance	~	
	Shock absorbers	~	
	Air Conditioning / Heater		
	Operation	~	
Interior Comments	Electrical / Accessories		
Seats Good	Head lights	~	
	Tail lights	~	
Carpets Good	Indicators	~	
Banala Good	Dashboard warning lights	~	
Panels	Wipers (front & rear)	~	
Dashboard Good	Window winder FL	~	
	Window winder FR		
General Comments	Window winder RL	~	
		~	
	Window winder RR	~	
	Rear view mirrors	~	
	Radio (basic test only)	~	
	CD (basic test only)	~	
	Number of keys	1	
Road Conditions During Test Drive: Dry	Central locking	~	
Engine Timing Mechanism: Timing Chain	Remote locking	~	
	Sat. Nav. (basic test only)	└──┤	~
Evidence of Cam Belt Replacement: Not Applicable Kms:	Reversing camera		~
Inspected by: Donovan Matara Date: 17 Apr 2019			

I have read and understood this condition guide.

Name: .....

Report ID: 18,007,584

Pass

V

V

V

V

1

17 Apr 2019

Fail

N/A

Version:

Created: