

Report ID: 18,010,878


Version: 1

Created: 23 Sep 2019

Make:	Ford	Model:	Mondeo	Body Style:	Hatchback
Year:	2015	Registration:	JHD758	Reg Expiry:	30 Nov 2019
WoF Expiry:	31 Aug 2020	Odometer:	124,570 Kms	Good No:	18010878
VIN:	WF0EXXWPCEFD6183	Next Service:	140000	Service History	y: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Dirty

Interior Comments					
Seats	Average				
Carpets	Average				
Panels	Good				
Dashboard	Good				

General Comments

Road Conditions During Test Drive: Dry

Timing Chain Engine Timing Mechanism:

Evidence of Cam Belt Replacement: Not Applicable Kms:

Stuart Melbourne 23 Sep 2019 Inspected by: Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	<i>y y</i>		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			1
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	5	.5	mm
Right front	(5	mm
Left rear	5	.5	mm
Right rear	5	.5	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	VVV		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)			
Window winder FL	\(\times \)		
Window winder FR	~		
Window winder RL	~		
Window winder RR			
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	1	
Central locking	'		
Remote locking	~		
Sat. Nav. (basic test only)	~		
Reversing camera	~		

Signature: