

## **Basic Vehicle Condition Guide**

Report ID: 18,011,089


Version:

Created: 10 Oct 2019

Make: Model: KIA Sportage **Body Style:** SUV Year: 2014 Registration: HGZ190 Reg Expiry: 24 Oct 2019 WoF Expiry: **Odometer:** 25 Sep 2020 272,724 Kms **Good No:** 18011089 VIN: U5YPC813SDL351843 Next Service: 282700 Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

L/H tail light broken.

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

OK.

Interior Comments		
Seats	Average	
Carpets	Average	
Panels	cargo blind missing.	
Dashboard	Average	

## **General Comments**

Nice AWD SUV.

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

**Daryll Timms** 16 Sep 2019 Inspected by:

Name: .....

Pass  V  V  V  V	Fail	N/A
V		
V		
V		
V		
V		
V V		
V V		
\( \sigma \)		1
<b>'</b>		
•		
		-
~		
~		
		~
~		
~		
V		
~		
d depth	of tyre	L es)
1	-	mm
4.0		mm
5.0		mm
6.0		mm
~		
~		
~		
V		
	1	
V		
<i>'</i>		
<i>'</i>		
<i>V</i>		
<i>v</i>		
<i>'</i>		
<b>V</b>		
<i>'</i>		$\vdash$
<i>y</i>		
<del>                                     </del>		
1		-
1		
_		
-		
	1	
~		
V		~
	<b>v v d</b> depth  4  5	マ

Signature: .....