

## **Basic Vehicle Condition Guide**

Report ID: 18,013,797


Version: 2

Created: 18 Nov 2019

Make: Model: Hyundai lload **Body Style:** Van Year: 2016 Registration: JYJ879 Reg Expiry: 28 Oct 2019 WoF Expiry: **Odometer: Good No:** 30 Jun 2020 22,933 Kms 18013797 VIN: KMFWBX7KMGU8328 Next Service: 35000 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Dry

**Conditions During Body Inspection:** 

**Under Carriage & Under Bonnet Inspection Comments** 

Tidy

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

	_
General	Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Stuart Melbourne Date: 01 Oct 2019

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	<ul><li>V</li><li>V</li><li>V</li></ul>		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V V</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		•	•
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	5	.4	mm
Right front	6.1		mm
Left rear	5.0		mm
Right rear	7.3		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			•
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\( \times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)			~
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

I have read and understood this condition guide.

Name: .....

Signature: .....