

Report ID: 18,014,122 Version: 2 08 Oct 2019 Created:

Make:	Ford	Model:	Mondeo	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2015	Registration:	JLT312	Reg Expiry:	02 Dec 2019	Engine		1	
WoF Expiry:	30 Nov 2019	Odometer:	144,008 Kms	Good No:	18014122	Oil level	~		
VIN:	WF0EXXWPCEFK2677	Next Service:	160000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC		SC D		D	Performance	r		
Key:	Lise (-0	SC D			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust W D D D D D D D D D D D D D D D D D D						Operation		~	
PT = paint defe				$\left[\left(\right) \right]$	7014	Noise	r		
C = crack					D SC	Clutch			~
P = pin dent	DIG HID				7414	CV joints	r		
* = decals D SC D B S SC						Wheel bearings	V		
SC = stone chips						Brakes			
W = significant scuffs SC W SC S D						Performance	~		
Body Incr	postion Commonts	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments Hail damage. SD card with consultant						Tyres (lowest observed tread depth of tyres)			es)
Hair dannage. 50 card with consultant						Left front 3 mn			mm
						Right front		4	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear		5	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	V		
						Shock absorbers	r		
						Air Conditioning / Heater			
L						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Trans seems to flare a little into 3rd at times						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
La une este el luca. Derine LISIL							10		
Inspected by: Brian Hill Date: 08 Oct 2019									

I have read and understood this condition guide.

Name:

Signature: