

Report ID: 18,014,356 Version: 1 Created: 07 Oct 2019

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2016	<b>Registration:</b>	JSU915	Reg Expiry:	12 Mar 2020	Engine	1		1
WoF Expiry:	11 Jun 2020	Odometer:	62,908 Kms	Good No:	18014356	Oil level	~		
VIN:	MMU148MK0GH6196	Next Service:	65,915kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	r		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional c	harge.	Coolant condition	~		1
						Performance	~		
Key:	P SC W	-0	SC P W	-01-	P SC	Radiator / Hoses (visual)	~		
S = scratch	AT.	A U		NG G	The second	Transmission			1
D = dent	SC 615					Operation	~		
R = rust PT = paint def				$\left( \left  \right\rangle \right)$		Noise	~		
C = crack					P	Clutch			~
P = pin dent					741L	CV joints	~		
* = decals	sc 916			-No-	ELL SC	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs P S S P S P P S C W						Performance			
		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body inspection comments						Tyres (lowest observed tread	•	of tyre	l es)
Detachable tow bar.						Left front	4		 
						Right front	7		 mm
						Left rear		.) 5	mm
Condition	- Durin a De du la c		2			Right rear			mm
Conditions During Body Inspection: Dry						Spare	-		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
OK.		•				Suspension performance	~		1
014						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation			1
Interior Comments						Electrical / Accessories	~		
Canto	Average					Head lights			1
Seats						Tail lights	~ ~		
Carpets	Average								
	Average					Indicators	V 		
Panels						Dashboard warning lights	V		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General	omments					Window winder FR	~		<u> </u>
General Comments Tidy 4WD d/cab ute.						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		_
						CD (basic test only)			~
L						Number of keys	2		1
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Remote locking	~		<u> </u>
						Sat. Nav. (basic test only)			~
Evidence	or Cam Beit Replac	ement: N	10	Kms:		Reversing camera	~		
Inspecte	d by: Daryll Timms	Date: 07 Oct 2019							
I have read	and understood th	is condition c	uide. Name: .			Signature:			