

Report ID: 18,014,552 Version: 2 13 Dec 2019 Created:

Make:	Mitsubishi	Model:	Outlander	Body Style:	SUV		Pass	Fail	N/A
Year:	2016	Registration:		Reg Expiry:	29 Oct 2019	Engine		-	<u> </u>
WoF Expiry:	15 Oct 2020	Odometer:	103,648 Kms	Good No:	18014552	Oil level	~		
VIN:	JMFXTGF8WGZ00506	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		<u> </u>
	port is not a warranty		с I II	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	s sc	-0	SC S SC		S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	S D SC			The	S SC	Operation	~		
R = rust PT = paint def				10	JHIH	Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		
* = decals	s sc PIP			AL.	HIP I	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D S SC S SC D						Performance	~		<u> </u>
		Note: son	ne defects & blemishes	may not be disn		Hand Brake	~		
Body Insp	pection Comments			indy not be disp	ayea in the diagram			oftyre	
-						Tyres (lowest observed tread depth of tyres) Left front 5.9 mm			
						Right front			mm
						Left rear	8.		mm
								6.8 mm	
Conditions During Body Inspection: Dry						Right rear	6.8 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder bor	meenspeede	<u>Comments</u>			Suspension			<u> </u>
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			<u> </u>
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats						Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		ļ!
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		
Concret	<u>Comments</u>					Window winder FR	~		<u> </u>
						Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
L						Number of keys	2		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>
Engina Ti	ming Machanism	Time in a f	Chain			Remote locking	~		
-	ming Mechanism:	Timing (V.e		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Ian Dunn Date: 15 Oct 2019									

I have read and understood this condition guide.

Name: