

Report ID: 18,014,575 Version: 4 03 Dec 2019 Created:

Make:	Hyundai	Model:	Accent	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2016	Registration:	KBM469	Reg Expiry:	14 Jul 2019	Engine			I	
WoF Expiry:	15 Oct 2020	Odometer:	107,269 Kms	Good No:	18014575	Oil level	~			
VIN:	KMHCT51DMHU30404	Next Service:	,	Service Histor	y: Yes	Smoke & fumes	V			
						Performance	~			
	port is not a warranty		с I II		1 B AL	Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
		_				Performance	~			
Key:		-0	SC			Radiator / Hoses (visual)	~			
S = scratch							Transmission			
D = dent	GIE			the	EL SC	Operation	~			
R = rust				10	JHIK	Noise	~			
PT = paint defects C = crack				+		Clutch	•		~	
P = pin dent	Ho					CV joints	~		~	
* = decals	- MIK			AL-		Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs						Performance				
		Note: com	ne defects & blemishes			Hand Brake	レ レ			
Body Insp	pection Comments	1016.301	le delects & blemisties	inay not be disp	layed in the diagram		•	ofturo		
						Tyres (lowest observed tread depth of tyres)				
						Left front		.7	mm	
						Right front	5		mm	
						Left rear	4		mm	
Conditions During Body Inspection: Wet						Right rear	8.0 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare				
	inage a onder bor	ince inspectie	<u>eominents</u>			Suspension				
						Suspension performance	~			
						Steering performance	~			
	Shock absorbers	~								
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
Good						Electrical / Accessories				
Seats						Head lights	~			
Carpets	Good					Tail lights	~			
	Good					Indicators	~			
Panels	duod					Dashboard warning lights	~			
Dashboa	Good Good					Wipers (front & rear)	~			
						Window winder FL	~			
Concret	ommonts					Window winder FR	~			
<u>General Comments</u>						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Wet										
Engine Timing Mechanism: Timing Chain							~			
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: Beversing camera									~	
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected by: Ian Dunn Date: 11 Oct 2019										
Inspected by. Ian Datin Date: 11 Oct 2019										

I have read and understood this condition guide.

Name:

Signature: