

Report ID: 18,014,838 Version: 3 04 Nov 2019 Created:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	MKY40	Reg Expiry:	04 Jul 2020	Engine			
WoF Expiry:	21 Jun 2020	Odometer:	230,154 Kms	Good No:	18014838	Oil level	~		
VIN:	7A8GK0C0708204841	Next Service:	238,100kms	Service History	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SC S	-0	S SC P SC		sc	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent				The	HIL S	Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack					SC W	Clutch	-		~
P = pin dent	HID				74114	CV joints	~		-
* = decals	- 91E			The	ALL W	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC W S SC S SC S SC S SC S SC S SC S S						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	of tyre	
					Left front 5.0 mm				
						Right front	6.	-	 mm
						Left rear			mm
Conditions During Rody Inspections Dry						Right rear	3.0 mm 5.0 mm		
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
ОК	•	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
	Air Conditioning / Heater	•							
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Average						Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Demolo	cargo shel	f missing.				Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	I					Window winder FR	~		
General Comments						Window winder RL	~		
Nice higher	km little Swift hatch.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking			
Road Con	aitions During Test	Drive:	Dry			Remote locking	v		
Engine Ti	ning Mechanism:	Timing	Chain				~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			v
						Reversing camera			~
Inspected by: Daryll Timms Date: 04 Oct 2019									

I have read and understood this condition guide.

Name:

Signature: