



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	18,016,874
Version:	2
Created:	24 Sep 2019

Make:	Subaru	Body Style:	Sedan
Model:	Legacy	VIN:	7AT0GF0BX19011317
Year:	2004	Odometer:	92,655 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good	<div>Turners Certification Key:</div> <div>✓ = Pass</div> <div>✗ = Fail</div> <div>• = Not applicable for this vehicle</div>							
1	Battery	✓	31	Reversing Camera	•	55	Coolant Condition	✓	79		Sun Roof Operation	•					
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80		Front Windscreen (no chips)	Good					
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81		Back Windscreen (no chips)	Good					
4	High Stop Light	✓	Transmission and Drive		Suspension		58	Suspension Performance	✓		82	Side Windows (no chips)	Good				
5	Front Right Indicators	✓	34	Operation	✓	59	Steering Performance	✓	83		Front Wiper Blades	Good					
6	Front Left Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	84		Rear Wiper Blade	Good					
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front		7	mm	85	R/H Mirror	Good		
8	Rear Left Indicators	✓	37	CV Joints	✓	62	Right Front	7	mm		63	Left Rear	7	mm	86	L/H Mirror	Good
9	Reversing Lights	✓	38	Wheel Bearing	✓	64	Right Rear	7	mm		65	Spare	Yes	87	L/F Guard	Good	
10	Rear Reflectors	✓	39	Wheel Balance	✓	66	Tools	✓	88	R/F Guard	Good						
11	Hazard Lights	✓	40	Gearbox (Manual)	•	Interior		67	AC Operation	✓	89	L/H Doors	Good				
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	68	Heater Fan	✓	90	R/H Doors	Good						
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable	69	Seatbelts	✓	91	L/H Sill	Good						
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		70	Horn	✓	92	R/H Sill	Good						
15	Number Plate Light	✓	Brakes				71	Seat Heaters	✓	93	Boot/Tail Gate	Good					
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	72	Sun Visors	✓	94	Front Bumper	Good						
17	Speedo	✓	45	Rear Brakes	✓	73	Sun Visors Lights/Mirrors	✓	95	Rear Bumper	Good						
18	Odometer	✓	46	Handbrake	✓	74	Seats	Good	96	Roof	Good						
19	Rev Counter	✓	Keys and Locking				75	Carpets	Good	97	Bonnet	Good					
20	Fuel Gauge	✓	47	Central Locking	✓	76	Panels	Good	98	Fuel Cap	✓						
21	Wipers Front/Rear	✓	48	Remote Locking	✓	77	Dashboard	Good	99	Mud Flaps	✓						
22	Window Opener FL	✓	49	Number of Keys	1			100	WOF	✓							
23	Window Opener FR	✓	Engine														
24	Window Opener RL	✓	50	Oil Level	✓												
25	Window Opener RR	✓	51	Smokes and Fumes	✓												
26	Rear View Mirrors	✓	52	Performance	✓												
27	Radio (Basic Test Only)	✓	53	Noise	✓												
28	CD (Basic Test Only)	✓	54	Starter Motor	✓												
29	Boot Open Switch	✓															

Inspected by:	Daryll Timms	Date:	24 Sep 2019
I have read and understood this condition guide:			
Name:		Signature:	