

Conditions During	Body Inspection
	a body mapeetion.

Under Carriage & Under Bonnet Inspection Comments OK.

Dry

			Air Conditioning / Heater		
			Operation	~	
Interior Comments			Electrical / Accessories		
Seats	average, fitted seat covers on front seats.		Head lights	~	
Correcto	Average	Tail lights	~		
Carpets '		Indicators	~		
Panels	Average		Dashboard warning lights	~	
Dashboard Average	Average		Wipers (front & rear)	~	
			Window winder FL	~	
			Window winder FR	~	
General Comments Good 2WD d/cab ute.			Window winder RL	~	
			Window winder RR	~	
			Rear view mirrors	~	
			Radio (basic test only)	~	
		CD (basic test only)	~		
		Number of keys	3		
Road Conditions During Test Drive: Dry			Central locking	~	
		Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:		Sat. Nav. (basic test only)		~	
			Reversing camera		~
Inspected by: Daryll Timms Date: 02 May 2019					

I have read and understood this condition guide.

Name:

N/A

V

mm

mm

mm

mm

8

V

V

V

Yes

Right rear

Suspension

Suspension performance

Steering performance

Shock absorbers

Spare