

Basic Vehicle Condition Guide

Report ID: 18,017,211


Version: 2

Created: 28 Jul 2019

Make: Model: Mazda Tribute **Body Style:** SUV Year: 2005 Registration: CNF22 Reg Expiry: 22 Oct 2019 WoF Expiry: **Odometer: Good No:** 01 Sep 2019 128,405 Kms 18017211 VIN: JM0CU081Y41205985 Next Service: 138400 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection:	Dry
------------------------------------	-----

Under Carriage & Under Bonnet Inspection Comments

OK, dirty.

Interior Comments	<u>S</u>
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments

Good AWD SUV.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Daryll Timms Inspected by:

Name:

ン ン ン		
V V V		
V V V		
ν ν		
'		
~		
v v		
~		
~		
~		
		~
~		
~		
~		
~		
depth	of tyre	 es)
	-	mm
	103	
~		
~		
~		
~		
~		
~		
~		
~		
<u> </u>		
· ·		
•		
•		
•		
•		
۷		
•		
		<u> </u>
		'
		'
	v v v depth 55 66 77	マ

Signature: