

## **Basic Vehicle Condition Guide**

Report ID: 18,017,398

Version: 2


Created: 05 May 2019

Fail N/A

Make: Model: Hyundai Tucson **Body Style:** SUV Year: 2009 Registration: FAM720 Reg Expiry: 30 Jun 2019 **WoF Expiry: Odometer:** 21 Jun 2019 139,557 Kms **Good No:** 18017398 VIN: KMHJN81BR9U09346( Next Service: 149600 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Minor stone chips front screen. No cargo blind

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

Brian Hill

**Evidence of Cam Belt Replacement:** Yes Kms: 93,679

Engine						
Oil level	~					
Smoke & fumes	\( \times \)					
Performance	~					
Noise	~					
Cooling System						
Coolant condition	~					
Performance	<b>'</b>					
Radiator / Hoses (visual)	<b>'</b>					
Transmission						
Operation	>					
Noise	>					
Clutch			>			
CV joints	~					
Wheel bearings	>					
Brakes						
Performance	>					
Hand Brake	~					
Tyres (lowest observed tread	l depth	of tyre	s)			
Left front	5	.0	mm			
Right front	5	.0	mm			
Left rear	3.0		mm			
Right rear	4.0		mm			
Spare		Yes				
Suspension						
Suspension performance	~					
Steering performance	\( \times \)					
Shock absorbers	~					
Air Conditioning / Heater						
Operation	~					
Electrical / Accessories						
Head lights	~					
Tail lights	~					
Indicators	~					
Dashboard warning lights	<ul><li>V</li><li>V</li><li>V</li></ul>					
Wipers (front & rear)	~					
Window winder FL	~					
Window winder FR	~					
Window winder RL	~					
Window winder RR	<b>'</b>					
Rear view mirrors	~					
Radio (basic test only)	~					
CD (basic test only)	~					
Number of keys	1					
Central locking	~					
Remote locking	~					
Sat. Nav. (basic test only)			~			

I have read and understood this condition guide.

Name: .....

Signature: .....

01 May 2019

Reversing camera

Date: