


<b>Make:</b>	Mitsubishi	<b>Model:</b>	L300	<b>Body Style:</b>	Van
<b>Year:</b>	2006	<b>Registration:</b>	DPL200	<b>Reg Expiry:</b>	30 Jul 2019
<b>WoF Expiry:</b>	15 Apr 2020	<b>Odometer:</b>	139,330 Kms	<b>Good No:</b>	18017442
<b>VIN:</b>	JMAHNP14V7A80026	<b>Next Service:</b>	142000	<b>Service History:</b>	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Stone chips front screen. Right front inner wheel arch needs painting. Drivers door pocket missing.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

Slight oil leak

**Interior Comments**

Seats	Poor
Carpets	Poor
Panels	Poor
Dashboard	Average

**General Comments**

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints			✓
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	2.0	mm	
Right front	4.0	mm	
Left rear	5.0	mm	
Right rear	6.0	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation			✓
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors	✓		
Radio (basic test only)		✓	
CD (basic test only)		✓	
Number of keys	1		
Central locking		✓	
Remote locking		✓	
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Brian Hill

Date: 01 May 2019

I have read and understood this condition guide.

Name: .....

Signature: .....