

Basic Vehicle Condition Guide

Report ID: 18,017,806


Version: 1

Created: 01 May 2019

Make: Model: Holden Combo **Body Style:** Van Year: 2000 Registration: FPK936 Reg Expiry: 18 Dec 2019 **Odometer:** WoF Expiry: 10 Dec 2019 105,696 Kms **Good No:** 18017806 VIN: W0L0SBF25Y3015412 Next Service: **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Dirty

Surface rust

Interior Comments			
Seats	Poor		
Carpets	Poor		
Panels	Average		
Dashboard	Average		

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Stuart Melbourne Date: 01 May 2019

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V V</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	\(\times \) \(\t		
Noise	~		
Clutch	~		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	2	2	mm
Right front	- 2	2	mm
Left rear		3	mm
Right rear	3	3	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V V		
Shock absorbers	~		
Air Conditioning / Heater		1	
Operation	~		
Electrical / Accessories		ı	
Head lights	~		
Tail lights	\(\times \)		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL			~
Window winder FR			~
Window winder RL			~
Window winder RR			~
Rear view mirrors		~	
Radio (basic test only)		~	
CD (basic test only)			~
Number of keys	1		
Central locking	~		
Remote locking			-
Sat. Nav. (basic test only)			~
Reversing camera			

Signature: