

Report ID: 18,017,899 Version: 1 01 May 2019 Created:

Make:	Nissan	Model:	Elgrand	Body Style:	SUV		Pass	Fail	N/A
Year:	2004	Registration:	JPH398	Reg Expiry:	17 Apr 2019	Engine			1
WoF Expiry:	08 Jun 2019	Odometer:	226,113 Kms	Good No:	18017899	Oil level	~		
	7AT0DH6MX15104992	Next Service:		Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	o <mark>rt is not a warranty</mark>	anation is mode	for one and miles as	Dauta hava nat	heen dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0	S S	-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			The	SC SC	Operation	~		
R = rust PT = paint defe				$\int$	JHIH	Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints			~
* = decals	sc 916			The	EIIP I	Wheel bearings	~		-
SC = stone chips						Brakes			
W = significant	scuffs	$-\emptyset$	SD SD			Performance	~		
		Note: som	e defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread depth of tyres)			
R mirror broken						Left front 5 m			
						Right front	5		mm
						Left rear	6		mm
Conditions During Pody Inspection: Wat						Right rear	3 mm		
Conditions During Body Inspection: Wet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			<u> </u>
						Operation	~		
Interior Comments						Electrical / Accessories			I
Seats	RF holes					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		+
	A					Wipers (front & rear)	~		+
Dashboai	rd Average					Window winder FL	~		+
						Window winder FR	~		
General Comments					Window winder RL	~		+	
Brakes spon	gey					Window winder RR	~		<u> </u>
						Rear view mirrors	~		+
						Radio (basic test only)	~		+
						CD (basic test only)	~		+
						Number of keys	1		L
Boad Con	ditions During Test	Drive:	Wet			Central locking	~		
			wet			Remote locking	~		+
Engine Timing Mechanism: Timing Chain					Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:					Reversing camera	~		+	
Inspected by: Stuart Melbourne						Date: 01 May 2019			

I have read and understood this condition guide.

Name: .....

Signature: .....