

## **Basic Vehicle Condition Guide**

Report ID: 18,018,699


Version: 2

Created: 06 Aug 2019

Make: Model: Holden Colorado **Body Style:** Utility Year: 2013 Registration: **GUG493** Reg Expiry: 25 Jul 2019 **Good No:** WoF Expiry: **Odometer:** 23 May 2020 98,894 Kms 18018699 VIN: MMU148EH0DH62395 Next Service: 1.5k overdue **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



## **Body Inspection Comments**

Hole in Right taillight/Tailgate badge missing/mudflaps damaged

**Conditions During Body Inspection:** Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Rear wheel drive

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Wet

**Engine Timing Mechanism:** Cambelt

**Evidence of Cam Belt Replacement:** No Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	<ul><li>V</li><li>V</li><li>V</li></ul>		
Performance	~		
Noise	~		
Cooling System		•	
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission		•	•
Operation	~		
Noise	<i>V V</i>		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4.5		mm
Right front	4		mm
Left rear	3		mm
Right rear	6		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	>		
Electrical / Accessories			
Head lights	~		
Tail lights	>		
Indicators	~		
Dashboard warning lights	<ul><li>V</li><li>V</li><li>V</li><li>V</li></ul>		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	V		
Window winder RL	•		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~

I have read and understood this condition guide.

Name: .....

Signature: .....

06 Aug 2019

Reversing camera