

Report ID: 18,018,718 Version: 2 14 May 2019 Created:

Make:	Hyundai	Model:	ТВ	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005		JGP360	Reg Expiry:	01 Jul 2019	Engine			
	17 May 2019	Odometer:	82,684 Kms	Good No:	18018718	Oil level	~		
VIN:	KMHBT51HR5U40588			Service Histor		Smoke & fumes	~		
			51040		y . No	Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise			
							~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
Key:						Performance	~		
S = scratch						Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust	sc 96					Operation	~		
PT = paint def	ect N					Noise	~		
C = crack						Clutch			~
P = pin dent	sc dk				241 <u>1</u> 5	CV joints	~		
*= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
No parcel tray						Tyres (lowest observed tread depth of tyres)			
						Left front 5.0 mi			mm
						Right front	2	.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Day						Right rear		.0	mm
Conditions During Body Inspection: Dry						Spare	2	Yes	
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Very dirty		•				Suspension performance	~		
						Steering performance	~		
							-		-
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation	~		
						Electrical / Accessories			T
Seats	, weitige					Head lights	~		
Carpets	Average					Tail lights	~		
	A					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		1
						Number of keys	2	ı	
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		1
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	ļ.		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
	-								
Inspected by: Stuart Melbourne Date: 06 May 2019									
I have read and understood this condition guide. Name:									