

Report ID: 18,018,827 Version: 1 06 May 2019 Created:

Signature: .....

Make:	Mazda	Model:	Mazda6	Body Style:	Wagon		Pass	Fail	N/A
Year:	2010	Registration:	FQZ869	Reg Expiry:	26 Dec 2019	Engine			L
WoF Expiry:		Odometer:	189,550 Kms	Good No:	18018827	Oil level	~		
VIN:	JM0GH10F200210788	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		<u> </u>
	port is not a warranty		6	Danta harra nat		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
		_				Performance	~		
Key:		-0	LS	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			The	EII S	Operation	~		
R = rust PT = paint def				í In	THA	Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		
* = decals	sc 916			-NL	ETTP:	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs	$- \emptyset$				Performance	~		
		Note: son	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments			,,		Tyres (lowest observed tread	•	of tyre	 (کد
									mm
						Right front	4		 mm
						Left rear	3		mm
Conditions During Pody Inspection, Dr.						Right rear			 mm
Conditions During Body Inspection: Dry						Spare	3 mn Yes		
Under Carriage & Under Bonnet Inspection Comments						spare Yes			
Tidy	•	•				Suspension performance	~		
,						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Jeurs						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Good					Dashboard warning lights	~		<u> </u>
raneis						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		<u> </u>
						Window winder FR	~		
General Comments						Window winder RL	~		
Pulls right						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Road Conditions During Test Drive: Dry						Central locking	2		
Koad Con	attions During Test	Urive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	•		~
Evidence of Cam Belt Replacement: Not Applicable Kms:									
		I'				Reversing camera			~
Inspected by: Stuart Melbourne Date: 06 May 2019									

I have read and understood this condition guide.

Name: .....