

Report ID: 18,018,972 Version: 1 07 May 2019 Created:

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	Registration:	GHM443	Reg Expiry:	12 Oct 2019	Engine			<u> </u>
WoF Expiry:		Odometer:	126,797 Kms	Good No:	18018972	Oil level	~		
VIN:	WBAVA76000NL3258(Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0	ls			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	GIE			the		Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint defe C = crack				+		Clutch			~
P = pin dent	Ho					CV joints			~
* = decals	- MIK			AL-	ENR	Wheel bearings	~		
SC = stone chi		VA		A	& <u> </u>	Brakes	V		
W = significan	t scuffs	-			Is	Performance	~		
		Nata	ne defects & blemishes	may not be disn		Hand Brake	~		
Body Insp	pection Comments	10000.3011	le delects & blemisnes	inay not be disp	layed in the diagram		•	ofture	
						Tyres (lowest observed tread depth of tyres) Left front 3			
							3		mm
						Right front	4		mm
						Left rear	3 mm		
Conditions During Body Inspection: Wet						Right rear	3 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	No		
	mage & onder bor	<u>ince inspectie</u>	<u>in comments</u>			Suspension			
Tidy						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
stains						Electrical / Accessories			
Seats	Stans					Head lights	~		
Carpets	Good					Tail lights	~		
	Cood					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Canada						Window winder FR	~		
General	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	Drive:	Wet			Central locking	~		
	ning Mashaulau	T:	<u>Chain</u>			Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Stuart Melbourne Date: 07 May 2019									

I have read and understood this condition guide.

Name:

Signature: