

## **Basic Vehicle Condition Guide**

Report ID: 18,019,162

Pass

1

Version: 1

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Coolant condition

Created: 07 May 2019


Fail

N/A

Make: Model: Toyota Hiace **Body Style:** Van Year: 1996 Registration: DNZ754 Reg Expiry: 12 Jul 2019 **Odometer:** Good No: WoF Expiry: 16 Jul 2019 307,694 Kms 18019162 VIN: **Next Service:** 7A8H60F0806138354 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



R lens taped in

Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Dirty

Interior Comments						
9	Seats	RF hole				
(	Carpets	missing				
ı	Panels	Poor				
[	Dashboard	Poor				

_	_
Conoral	Comments
General	COMMENTS

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kms:

Performance	~			
Radiator / Hoses (visual)	~			
Transmission	,		•	
Operation	~			
Noise	~			
Clutch			~	
CV joints			~	
Wheel bearings	~			
Brakes	•			
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	depth	of tyre	es)	
Left front		7	mm	
Right front		5	mm	
Left rear		2	mm	
Right rear		5	mm	
Spare		Yes	Yes	
Suspension	,			
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	~			
Electrical / Accessories	•			
Head lights	~			
Tail lights	~			
Indicators	\( \times \)			
Dashboard warning lights	~			
Wipers (front & rear)	~			
Window winder FL		~		
Window winder FR	~			
Window winder RL			~	
Window winder RR			~	
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)		~		
Number of keys	2			
Central locking	~			
Remote locking			~	
Sat. Nav. (basic test only)			~	
Reversing camera			~	

Inspected by: Stuart Melbourne

de. Name: .....

Signature: .....

07 May 2019

Date: