Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	18,019,865
Version:	2
Created:	24 Sep 2019

Make:	Subaru	Body Style:	Sedan
Model:	Legacy	VIN:	7AT0GF0BX19015727
Year:	2006	Odometer:	83,771 Kms
Road Conditions During Test Drive:	Dry		

Electrical		
1	Battery	✓
2	Headlights	✓
3	Tail Lights	✓
4	High Stop Light	✓
5	Front Right Indicators	✓
6	Front Left Indicators	✓
7	Rear Right Indicators	✓
8	Rear Left Indicators	✓
9	Reversing Lights	✓
10	Rear Reflectors	✓
11	Hazard Lights	✓
12	Courtesy Lights	✓
13	Dashboard Lights	✓
14	Dashboard Dimmer Switch	✓
15	Number Plate Light	✓
16	Dashboard Warning Lights	✓
17	Speedo	✓
18	Odometer	✓
19	Rev Counter	✓
20	Fuel Gauge	✓
21	Wipers Front/Rear	✓
22	Window Opener FL	✓
23	Window Opener FR	✓
24	Window Opener RL	✓
25	Window Opener RR	✓
26	Rear View Mirrors	✓
27	Radio (Basic Test Only)	✓
28	CD (Basic Test Only)	✓
29	Boot Open Switch	✓
30	Fuel Flap Release	✓
31	Reversing Camera	•
32	USB Port	•
33	Window Lock Switch	✓

Transmission and Drive		
34	Operation	✓
35	Noise	✓
36	Clutch	•
37	CV Joints	✓
38	Wheel Bearing	✓
39	Wheel Balance	✓
40	Gearbox (Manual)	•
41	Engine Timing	Timing Chain
42	Evidence of Cam Belt Replacement	Not Applicable
43	Replaced at (odometer reading)	

Brakes		
44	Front Brakes	✓
45	Rear Brakes	✓
46	Handbrake	✓

Keys and Locking		
47	Central Locking	✓
48	Remote Locking	✓
49	Number of Keys	2

Engine		
50	Oil Level	✓
51	Smokes and Fumes	✓
52	Performance	✓
53	Noise	✓
54	Starter Motor	✓

Cooling System		
55	Coolant Condition	✓
56	Performance	✓
57	Radiator/Hoses (visual)	✓

Suspension		
58	Suspension Performance	✓
59	Steering Performance	✓
60	Shock Absorbers	✓

Wheels and Tyres			
61	Left Front	5	mm
62	Right Front	6	mm
63	Left Rear	4	mm
64	Right Rear	5	mm
65	Spare	Yes	
66	Tools		✓

Interior		
67	AC Operation	✓
68	Heater Fan	✓
69	Seatbelts	✓
70	Horn	✓
71	Seat Heaters	•
72	Sun Visors	✓
73	Sun Visors Lights/Mirrors	✓
74	Seats	Good
75	Carpets	Good
76	Panels	Good
77	Dashboard	Good

Exterior		
78	Under Carriage	Good
79	Sun Roof Operation	✓
80	Front Windscreen (no chips)	Good
81	Back Windscreen (no chips)	Good
82	Side Windows (no chips)	Good
83	Front Wiper Blades	Good
84	Rear Wiper Blade	Good
85	R/H Mirror	Good
86	L/H Mirror	Good
87	L/F Guard	Good
88	R/F Guard	Good
89	L/H Doors	Good
90	R/H Doors	Good
91	L/H Sill	Good
92	R/H Sill	Good
93	Boot/Tail Gate	Good
94	Front Bumper	Good
95	Rear Bumper	Good
96	Roof	Good
97	Bonnet	Good
98	Fuel Cap	✓
99	Mud Flaps	✓
100	WOF	✓

Turners Certification Key:

✓ = Pass

✕ = Fail

• = Not applicable for this vehicle

Inspected by:	Daryll Timms	Date:	24 Sep 2019

I have read and understood this condition guide:

Name:		Signature:	