

Report ID: 18,020,507 Version: 2 21 Jun 2019 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility]		Pass	Fail	N/A	
Year:	2012	Registration:	GPN580	Reg Expiry:	18 May 2019	Engine	Engine			L	
WoF Expiry:	24 May 2020	Odometer:	206,908 Kms	Good No:	18020507	Oil level		~			
VIN:	MR0EZ12G904012637	Next Service:	218000	Service Histor	y: Yes	Smoke & fur	nes	~			
						Performance	e	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise		~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System					
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition				
			* SC SC		SC	Performance	e	~			
Key:	S	-0	* SC SC	-01-		Radiator / He	oses (visual)	~			
S = scratch						Transmission	1			L	
D = dent R = rust S W A A A A A A A A A A A A A A A A A A								~			
PT = paint defect								~			
C = crack								~			
P = pin dent								~			
* = decals S O S D							ngs	~			
SC = stone chips						Brakes					
W = significant scuffs S SC S* S SC S D						Performance	~				
Rody Inspection Commonts Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		v			
body inspection comments							observed tread	-	of tyre	ـــــــــــــــــــــــــــــــــــــ	
Windscreen damaged									mm		
						Right front		8.	-	mm	
						Left rear	-			mm	
Conditions During Body Inspection: Dry						Right rear	Right rear		0	mm	
Conditions During Body Inspection: Dry						Spare Yes					
Under Carriage & Under Bonnet Inspection Comments						Suspension					
							performance	~			
						Steering per		~			
						Shock absor		~			
							Air Conditioning / Heater				
						Operation 🖌					
Interior Comments						Electrical / Accessories					
Seats	Seats Average				Head lights		~				
	A					Tail lights		v			
Carpets	Average					Indicators		· ·			
Panels	Good						warning lights	~		<u> </u>	
						Wipers (fron		• •			
Dashboa	Ird Good					Window win		v			
						Window win		• •			
General Comments						Window win		~			
						Window win		· ·			
						Rear view m		v			
						Radio (basic		v			
						CD (basic tes		· ·			
						Number of k		2			
Road Conditions During Test Drive: Dry						Central locki		2 V			
Road Conditions During Test Drive: Dry						Remote lock	-	• •			
Engine Timing Mechanism: Cambelt							sic test only)	-		~	
Evidence of Cam Belt Replacement: Yes Kms: 151,000						Reversing ca				~	
										_ -	
Inspected by: Chris Vanner Date: 20 Jun 2019											

I have read and understood this condition guide.

Name:

Signature: