

Report ID: 18,021,030

Version:


Created: 04 Sep 2019

Pass Fail N/A

Make:	Ford	Model:	Ranger	Body Style:	Utility
Year:	2014	Registration:	HRR57	Reg Expiry:	29 Dec 2019
WoF Expiry:	03 Sep 2020	Odometer:	100,311 Kms	Good No:	18021030
VIN:	MNAUMFF50EW29276	Next Service:	105000	Service History	y: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil seepage

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

2wd

Smoke from exhaust

Road Conditions During Test Drive: Dry

Timing Chain Engine Timing Mechanism:

Evidence of Cam Belt Replacement: Not Applicable Kms:

Bobby Zhong Inspected by:

Name:

Engine			
Oil level	~		
Smoke & fumes		~	
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	>		
Tyres (lowest observed treac	depth	of tyre	es)
Left front		5	mm
Right front		5	mm
Left rear	4		mm
Right rear		4	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	'		
Date: 04 Sep 201	19		

Signature: