

Report ID: 18,022,398 Version: 3 12 Sep 2019 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	Registration:	GYG567	Reg Expiry:	19 Sep 2019	Engine			
WoF Expiry:		Odometer:	61,398 Kms	Good No:	18022398	Oil level	~		
VIN:	MNTCPGD22A000082	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
Note: This re	port is not a warranty	avation is made	for one and miles as	Dauta hava nat	heen discontinuing or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	*W SC	-01-	SC	Radiator / Hoses (visual)	~		
S = scratch	STE			NG G	<u>کھر</u>	Transmission			1
D = dent R = rust	- HE			TIS		Operation	~		<u> </u>
PT = paint def	ect NP			$\left[ \right] \left[ \right]$		Noise	~		
C = crack						Clutch	~		
P = pin dent	HID				74114	CV joints	~		<u> </u>
* = decals	sc die			The second		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan	t scuffs SC		* SC SC		SC	Performance	~		
Body Inc	position Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
								mm	
						Right front		0.0	mm
						Left rear	8	.0	mm
Conditions During Body Inspection: Dry						Right rear		.0	mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1	1	.I
						Operation	~		
Interior Comments						Electrical / Accessories	1		
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		1
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		1
Dashboa	ird					Window winder FL		V	
						Window winder FR	~		
General Comments					Window winder RL	~			
L/F Windov	v not working					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		•
Road Conditions During Test Drive: Dry						Central locking	~		
			·			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
							-		
Inspecte	d by: Chris Vanner					Date: 19 Jul 201	9		

I have read and understood this condition guide.

Name: .....