

Report ID: 18,022,572 Version: 1 09 Aug 2019 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A	
Year:	2013	Registration:	HDA89	Reg Expiry:	06 Nov 2019	Engine			L	
WoF Expiry:	05 Nov 2019	Odometer:	132,018 Kms	Good No:	18022572	Oil level	~			
VIN:	MMAJNKB40DD00996	Next Service:	137000	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for ago and miloago	Parts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~			
					Draw	Performance	~			
Key:	SC W	-0	sc sc	-01-	D SC W	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	SC 6/6			15		Operation	~			
R = rust PT = paint def				\prod		Noise	~			
C = crack						Clutch	~			
P = pin dent					게비	CV joints	~			
* = decals	sc 916			The	ELL SC W	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs W SC SC SC SC SC SC W						Performance	~			
		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)				
· ·									mm	
						Right front	9.		mm	
						Left rear	7.		mm	
Conditions Duving Pody Inspection						Right rear		7.0 mm		
Conditions During Body Inspection: Dry						Spare				
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension				
	-	·				Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats Good						Head lights	~			
						Tail lights	~			
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~			
raneis						Wipers (front & rear)	~			
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	~			
General C	Comments					Window winder RL	~			
Left rear tail light cracked						Window winder RR	v v			
						Rear view mirrors	v v			
						Radio (basic test only)	v v			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry						Central locking	2			
Koad Con	attions During Test	Urive:	Dry			Remote locking	v v			
Engine Ti	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)	•		~	
Evidence of Cam Belt Replacement: Yes Kms: 92,851						Reversing camera			~	
Inspected by: Chris Vanner Date: 18 Jul 2019										

I have read and understood this condition guide.

Name:

Signature: