

Basic Vehicle Condition Guide

Report ID: 18,023,290


Version: 5

Created: 21 Aug 2019

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2016 Registration: JZU733 Reg Expiry: 17 Aug 2020 WoF Expiry: **Odometer: Good No:** 18 Aug 2020 47,145 Kms 18023290 VIN: KMHSU81XSGU66041 **Next Service:** 52000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Chris Vanner Date: 26 Jul 2019

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	Pass V V V V V V V V V V	Fail	N/A
Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance			
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance			
Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	\(\frac{\psi}{\psi} \)		
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V V V V V V V V V V V V V V V V V		
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V V		
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V V		
Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V V		
Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V		
Transmission Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V V		
Operation Noise Clutch CV joints Wheel bearings Brakes Performance	V V		
Noise Clutch CV joints Wheel bearings Brakes Performance	ν ν ν		
Clutch CV joints Wheel bearings Brakes Performance	ν ν		ı
CV joints Wheel bearings Brakes Performance	ν ν		
Wheel bearings Brakes Performance	v v		~
Brakes Performance	~		
Performance			
	~		
Hand Brake	~		
Tyres (lowest observed tread of	depth	of tyre	! :s)
Left front	3.	.0	mm
Right front	3.0		mm
Left rear	3.0		mm
Right rear	3.	.0	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			I
Operation	~		
Electrical / Accessories			
Head lights	·		
Tail lights	·		
Indicators	v		
Dashboard warning lights	·		
Wipers (front & rear)	<u></u>		
Window winder FL	<u></u>		
Window winder FR	~		
Window winder RL	~		
Window winder RR	<u> </u>		
Rear view mirrors	~		
Radio (basic test only)	<u> </u>		
CD (basic test only)	<u> </u>		
- · · · · · · · · · · · · · · · · · · ·	2		
Central locking			
	<u>/</u>		
Remote locking	<u> </u>		
1 Sat Nav (bacic tact only)	·		
Sat. Nav. (basic test only) Reversing camera	<u> </u>		

I have read and understood this condition guide.

Name:

Signature: