

## **Basic Vehicle Condition Guide**

Report ID: 18,023,773

Pass

1

V

/

V

1

J

Version:

Engine

Oil level

Noise

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

**Electrical / Accessories** 

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Smoke & fumes

Performance

Cooling System

Created: 28 Aug 2019

Fail

N/A

mm

mm

mm

 $\mathsf{mm}$ 

1.0

2.0

2.0

2.0

1

/

/

1

1


2

Yes

Make: Nissan Model: Navara **Body Style:** Utility Year: 2014 Registration: HNS612 **Reg Expiry:** 28 Oct 2019 WoF Expiry: **Odometer:** 27 Jul 2019 33,440 Kms **Good No:** 18023773 VIN: MNTCPGD22A000096 Next Service: 36000 **Service History:** Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

Chris Vanner

**Evidence of Cam Belt Replacement:** No

	Central locking	V				
	Remote locking	V				
	Sat. Nav. (basic test only)		~			
Kms:	Reversing camera		~			
Date: 28 Aug 2019						
Name: Signature:						