

	Performance	~	
<u>Note: This report is not a warranty</u> This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled o	or Noise	~	
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommend a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	ds Cooling System		
a fuil mechanical inspection prior to purchase and this can be arranged for an additional charge.	Coolant condition	~	
Marina D SC SPSCW SDW	Performance	~	
Key:	Radiator / Hoses (visual)	~	
S = scratch D = dent	Transmission	11-	
R = rust SC AR SC SC	Operation	~	
PT = paint defect	Noise	~	
C = crack	Clutch	~	
P = pin dent	CV joints	~	
* = decals SC 919	Wheel bearings	~	
SC = stone chips	Brakes	I	
W = significant scuffs SC SC W D W D W	Performance	~	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram	n Hand Brake	~	
	Tyres (lowest observed trea	d depth	of tyres)
	Left front	6.0	) mm
	Right front	6.0	) mm
	Left rear	6.0	) mm
Conditions During Body Inspection: Dry	Right rear	6.0	) mm
	Spare		Yes
Under Carriage & Under Bonnet Inspection Comments	Suspension		
	Suspension performance	~	
	Steering performance	~	
	Shock absorbers	~	
	Air Conditioning / Heater		<b>.</b>
	Operation	~	
Interior Comments	Electrical / Accessories		<b>i</b>
Seats Good	Head lights	~	
Good	Tail lights	~	
Carpets	Indicators	~	
Panels Good	Dashboard warning lights	~	
Good	Wipers (front & rear)	~	
Dashboard	Window winder FL	~	
	Window winder FR	~	
General Comments	Window winder RL		~
	Window winder RR		~
	Rear view mirrors	~	
	Radio (basic test only)	~	
	CD (basic test only)	~	
	Number of keys	1	
Road Conditions During Test Drive: Dry	Central locking	~	
- · ·	Remote locking	~	
Engine Timing Mechanism: Cambelt	Sat. Nav. (basic test only)		~
Evidence of Cam Belt Replacement: No Kms:	Reversing camera		~
Inspected by: Chris Vanner	Date: 02 Sep 20	19	

I have read and understood this condition guide.

Name: .....

Report ID: 18,024,500 3

Version: 22 Nov 2019 Created:

Pass

V

V

Fail

N/A