

Report ID: 18,075,869 Version: 1 08 Jun 2018 Created:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,007	Registration:		Reg Expiry:		Engine	I		L
WoF Expiry:		Odometer:	125,541 Kms	Good No:	18075869	Oil level	~		
VIN:	7AT0GK0CX18113011	Next Service:	135,000kms	Service Histor	y: No	Smoke & fumes	~		
			·			Performance	~		
	port is not a warranty	avation is made	for one and miles as	Dauta hava nat	hoon dismonthed on	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	nical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
		_				Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent				The	EIU/	Operation	~		
R = rust PT = paint defe				\int		Noise	~		
C = crack				$+ \mathbf{\nabla}$		Clutch	~		
P = pin dent					세비	CV joints	~		
* = decals	616			-NL	ETTP-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: son	ne defects & blemishes	mav not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread		of tyre	() ()
No spare wheel, factory repair kit only .						Left front 4 mm			
						Right front			 mm
						Left rear			mm
			_			Right rear	4		 mm
Conditions During Body Inspection: Dry						Spare			
Under Carriage & Under Bonnet Inspection Comments						Spare No			
Tidy .	j					Suspension performance			
lidy.						Steering performance	~		
						Shock absorbers			
						Air Conditioning / Heater	~		
Interior Comments						Operation			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
General (omments					Window winder FR	~		
General Comments Nice bright Swift sport.					Window winder RL	~			
	·					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ming Mechanism	Timina	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence		ement: N	lot Applicable	NIIIS;		Reversing camera			~
Inspected by: Daryll Timms Date: 08 Jun 2018									

I have read and understood this condition guide.

Name:

Signature: