

Report ID: 18,075,922


Version:

Created: 11 Jun 2018

Make:	Honda	Model:	Stream	Body Style:	Hatchback
Year:	2,007	Registration:		Reg Expiry:	
WoF Expiry:	05 Jun 2019	Odometer:	98,829 Kms	Good No:	18075922
VIN:	7AT08GADX18042715	Next Service:	108824	Service History	/: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>					
Seats	Good				
Carpets	Good				
Panels	Good				
Dashboard	Good				

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

07 Jun 2018 Inspected by: **Bobby Zhong** Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	v v		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	4	.0	mm
Right front	4.0		mm
Left rear	4.0		mm
Right rear	6.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			1
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL			
Window winder FR	\(\times \)		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	1	1
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~

Signature: