

Report ID: 18,077,032 Version: 2 Created: 05 Sep 2018

Make:	Ford	Model:	Territory	Body Style:	SUV		Pass	Fail	N/A
Year:	2,014	Registration:	HPQ87	Reg Expiry:	13 Aug 2018	Engine	1		
WoF Expiry:	21 Jun 2019	Odometer:	137,700 Kms	Good No:	18077032	Oil level	~		
VIN:	6FPAAAJGATDE53757	Next Service:	151000	Service Histor	y: No	Smoke & fumes	V		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	V		
						Performance	V		
Key:		-0		-01-	SP	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust				715	HIV	Operation	V		
PT = paint defe				$\left(\left \left(\right) \right\rangle \right)$	7011	Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				74JUL	CV joints	~		
* = decals	PSC 916			To .	ELC'S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significant	W					Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	ft front 4.0		mm
						Right front	4	.0	mm
						Left rear	8	.0	mm
Conditions During Body Inspection: Dry						Right rear	8.0 mm		mm
						Spare Yes		Yes	
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Stains					Head lights	~		
Comoto	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Deckler	rd Average					Wipers (front & rear)	~		
Dashboa	iu y					Window winder FL	~		
	-					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	Central locking	~							
	ning Mashaultur	<u> </u>	Dry			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:									~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera		~	
Inspected by: Stuart Melbourne Date: 29 Jun 2018									

I have read and understood this condition guide.

Name:

Signature: